



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Framing

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Carpenters

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety glasses, hearing protection, gloves

WESTERN HAZARD CATEGORY*

Energy/Tools or Equipment/Work Site Hazards

HAZARD TYPE*

Electricity/Hand Tools/Falling Objects

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 28, 2017

WRITTEN BY:

Ted Chelchowski

REVIEWED BY:

Structural Shop

MGMT APPROVAL:

Randy Regier

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

Building walls & bulkheads using metal or wooden studs	Cuts or slivers	Wear proper PPE
Using power and hand tools	Framing falling over	Secure existing framing
	Bruising from swinging hammer	Be alert of other workers around you
	Fastening into live wires	Survey area when fastening into existing materials
		Inspect all power tools before plugging in
		Inspect hand tools before use